

Profondità minima di serraggio

Minimum clamping length

La profondità di serraggio è indicata con il simbolo K. Attenzione! La profondità minima di serraggio indicata sul gambo è conforme alle indicazioni europee sulla sicurezza e non indica la profondità di serraggio ottimale, bensì quella minima! La procedura corretta prevede di inserire il gambo in profondità nel mandrino, per quanto possibile, e di verificare che l'utensile fuoriesca dal mandrino il meno possibile.

The minimum clamping length is labelled by the symbol K. Important: the minimum clamping length labelled on the shank corresponds to European safety requirements and is therefore not the most suitable clamping length – it only represents the minimum length! The shank should be clamped within the chuck as deeply as possible, and the degree to which the tool protrudes from the chuck should be kept to a minimum.

Figura 1: secondo norma (non ottimale)

Figure 1: according to the standard (not ideal)




Figura 2: serraggio ottimale (ottimale!)

Figure 2: optimum clamping (ideal!)




Figura 3: serraggio troppo profondo (non ottimale)

Figure 3: shank clamped too deeply within the chuck (not ideal)

